

Complaint from Worston

Parish Meeting

As instructed I have made enquiries as to who has previously repaired these paths.

With regard to the bridge path I think the part they complain about is the short length of about 20 yards from our road, just through the gate into the field, as it is always very dirty in wet weather, but I consider whatever was done to it it would always be more or less dirty as the cattle tread it up. I am informed that the other end of this path on the St. Bridgeford side of the brook, has been previously repaired by the parish but this length is more of the nature of

D659/5/33 (1903) Surveyors of Highways report book

the other time had the return for

Worston Parishes

Regarding the length of road running from the bottom of the railway bridge to the Worston house. I cannot find out whether this has ever been repaired by the parish but I consider it can only be tested upon an a public foot path as the short length of road only goes so far as the Worston house and is of no benefit to anyone but them. I believe all they complain about here is its dirty state.

a road as it has a hedge on each side.

14.286

41

7.148

31  
4.061

268

46  
211

C.B.

THE BROOK DIVIDING GREAT BRIDGEFORD  
FROM WORSTON AS STATED  
ON SURVEYORS REPORT BOOK.

30  
8.767

104  
1.545

268

110  
4.335

105  
3.303

Cherry Lane

106  
7.244

111  
8.730

109  
1.988

Bridgeford Hall

108  
1.283

139  
.457

E.M. 280.4

6  
204

138  
1.338

140  
1.320

142  
333

M.P.

137

Aqueduct

141  
2.199

274

Great I

Overflows

Sluice

Sluice

Sluice

Corn Mill

149  
1.570

147  
1.393

275

150  
.854

148  
567

152  
3.998

S.P.

S.P.

G.P.

E.M. 278.4

274

S.P.

S.P.

G.P.

146  
1.167

Station

173  
469

175  
2.923